
1

D

This print and associated documents and the contained information are the confidential property of ELECTRONIC CABLE SPECIALISTS. Disclosure of, and/or reproduction of, all or part thereof or manufacture of any part from information contained on this print not specifically permitted by ELECTRONIC CABLE SPECIALISTS in writing is forbidden.



D





© © LOCKWASHER (4) RUBBER WASHER (4)

DIMENSIONS A RETAINING RING

SPECIFICATIONS

ELECTRICAL

IMPEDANCE: 50 OHMS NOMINAL FREQUENCY RANGE: 0-6 GHz VSWR: 1.70:1 MAXIMUM

INSERTION LOSS: 0.3 dB • 6 GHz

WORKING VOLTAGE: 1000 VRMS © SEA LEVEL
DIELECTRIC WITHSTANDING: 2500 VRMS © SEA LEVEL
INSULATION RESISTANCE: 5000 MEGOHMS MINIMUM
© 500 VOLTS DC

MECHANICAL

MECHANICAL INTERFACE PER ARINC SPEC 600 FIGURE 19-54.2 (SIZE 1)
TERMINATION STYLE: CENTER CONTACT-SOLDER

FERRULE-CRIMP

CABLE RETENTION: 60 LBS

ENVIRONMENTAL

TEMPERATURE RATING: -65' TO +200' VIBRATION: MIL-STD-202, METHOD 204, COND. B SHOCK: MIL-STD-202, METHOD 213, COND. I THERMAL SHOCK: MIL-STD-202, METHOD 107, COND. B CORROSION: MIL-STD-202, METHOD 101, COND. B MOISTURE RESISTANCE: MIL-STD-202, METHOD 106

MATERIALS

BODY: BRASS PER QQ-B-626

FERRULE: ANNEALED BRASS PER QQ-B-626


CENTER CONTACT: BERYLLIUM COPPER PER QQ-C-530 DIELECTRIC: TEFLON PER L-P-403

FINISHES


FERRULE: BRIGHT NICKEL PER QQ-N-290
BODY, CENTER CONTACT: GOLD PER MIL-G-45204

## INSTALLATION INSTRUCTIONS


1. BEGIN BY CUTTING THE CABLE OFF SQUARE.



2. WHEN USING AUTOMATIC STRIPPING EQUIPMENT, STRIP CABLE AS SHOWN STARTING WITH L1 AND ENDING WITH L3. TAKE CARE NOT TO NICK THE CONDUCTORS WHILE STRIPPING THE DIELECTRIC AND JACKET. IF AUTOMATIC STRIPPING EQUIPMENT IS NOT AVAILABLE, STRIP ONLY L1 AND L3 AND TRIM EXCESS BRAID AT STEP 10.




3. SLIDE THE FERRULE AND ADHESIVE SHRINK TUBING 1



4. SOLDER THE CONTACT ONTO THE CENTER CONDUCTOR, PER MIL—STD—2000, USING 63Sn/37Pb SOLDER. ENSURE THE CONTACT IS BUTTED AGAINST THE CABLE DIELECTRIC. CLEAN ALL FLUX RESIDUES USING APPROPRIATE FLUX CLEANER.




USING TWEEZERS, FOLD THE OUTER BRAID BACK OVER THE CABLE JACKET, LEAVING AS MUCH WEAVE AS POSSIBLE.



 SLICE THE ALUMINUM/POLYESTER FOIL LENGTHWISE ABOUT EVERY 1/8". GENTLE ROTATE PIN TO SEPARATE THE FLAT FOIL BRAID AND ALUMINUM/POLYESTER FOIL FROM THE DIELECTRIC. USING TWEEZERS, FOLD BACK ALUMINUM/POLYESTER FOIL OVER THE OUTER BRAID.




 USING TWEEZERS, FOLD THE INNER BRAID BACK OVER THE OTHER SHIELDS, LEAVING AS MUCH WEAVE AS POSSIBLE. NOTE: DO NOT UNRAVEL DIELECTRIC WHEN PULLING BACK OUTER SHIELD.



REVISIONS DESCRIPTION ECN ZONE REV. DATE APPROVED 21604 - N/C NEW RELEASE. 12/20/04 DEK 30011 C2 A CHG STRIP DIM FROM .31/.40/.70 TO .19/.31/.62|8/16/07 CAC B NOTE 4 DEL "OR CRIMP WITH Y1757 DIE" 40648 C3 7/16/10 DEK TERM STYLE SPEC, DELETED "CRIMP" 45747 A4 C BODY FINISH WAS BRIGHT NICKEL 1/12/12


8. SLIDE THE BODY OF THE CONNECTOR OVER THE END OF THE CABLE UNTIL THE NOTCH IN THE CONTACT SEATS INTO THE DIELECTRIC RIDGE INSIDE THE CONNECTOR BODY.



 FOLD ALL THREE BRAIDS UP OVER THE NECK OF THE CONNECTOR BODY.



10. SLIDE THE FERRULE UP OVER THE SHIELDS AND AGAINST THE CONNECTOR BODY. TRIM AWAY ANY EXCESS BRAID. CRIMP THE FERRULE ONCE, NEXT TO THE BODY, USING THE M22520/5-31 DIE IN A M22520/5-01 TOOL FRAME. APPLY ADHESIVE HEAT SHRINK.



NOTES

1 ENSURE HEAT SHRINK IS INSTALLED PRIOR TO CRIMPING CONNECTOR.

ADHESIVE HEAT SHRINK SHOULD BE APPLIED IN ACCORDANCE WITH ECS WORK INSTRUCTION WI007. CONTACT ECS FOR A COPY OF THIS WORK INSTRUCTION.

3. CONNECTOR DIMENSIONS ARE FOR REFERENCE ONLY.

ALL LENGTHS IN	INCHES		E C S	<u>,</u>	ELEC	CTRONIC CABLE SPECIALISTS FRANKLIN, WI 53132 PHONE: (414) 421-5300
APPROVALS	DATE	TITLE			CTOL	
DRAWN BY: C CHAPMAN	12/14/04	SIZE 1, ARINC 600, RF CONNECTOR FOR ECS CABLE 310701				
CHECKED BY: D KNOLL	12/20/04					
DESIGNED BY:		SIZE	CAGE C	ODE	LEVEL	
PROJECT ENG:		IB.	1661	197	7	L0102
ENG. MGR: D KNOLL	12/20/04	SCALE:		j	EFFECTIVITY:	Y: SHEET: 1 OF 2

4

3

2

1

